Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080058-0

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

No. 11843

RECEIVED FROM PLANT #2

DATE REC'D 4-10-57

P.O. NO.

VENDOR PACKING SLIP NO.

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH NO. OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R ACCT. OR W.O. NO.
322		298	C	13				

CHARGE TO

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
200	731587 Rubber Chin	200		
	IR #5038			

RECEIVED BY [illegible] INSPECTED BY [illegible] DATE 4-11-57 REJECTS RETURNED ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

3761 E. COLORADO ST., PASADENA, CALIF.

No. 11860

RECEIVED FROM PLANT #2

DATE REC'D 4-10-57

P.O. NO.

VENDOR PACKING SLIP NO.

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH NO. OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R ACCT. OR W.O. NO.
322		298	C	13				

CHARGE TO

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
10	731459-2 Crystal Timer	10		
	IR #5350			

RECEIVED BY [illegible] INSPECTED BY [illegible] DATE 4-11-57 REJECTS RETURNED ON SHIP. MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080058-0